Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080004-9

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

7961 E. COLORADO ST., PASADENA, CALIF.

No. 11009

RECEIVED FROM

DATE REC'D. 1-24-57

P.O. NO.

VENDOR PACKING SLIP NO.

PIN # 9

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O K	ACCT. OR W.O. NO.	S.O. NO.
322	000000	10021	C	0	00	00				

CHARGE TO

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
20	731458 DISC.	20 ✓		

SHIP MEMO 85889

RECEIVED BY [signature] HMC-1069

INSPECTED BY Dwa DATE 1/25/57

REJECTS RETURNED ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

7961 E. COLORADO ST., PASADENA, CALIF.

No. 11017

RECEIVED FROM

DATE REC'D. 1-24-57

P.O. NO.

VENDOR PACKING SLIP NO.

PIN # 9

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	R	ACCT. OR W.O. NO.	S.O. NO.
322	000000	10008	C	0	00	00				

CHARGE TO

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
35	731338 INSULATOR CONTACT NA731320	35 ✓		

SHIP MEMO 85890

RECEIVED BY [signature] HMC-1069

INSPECTED BY Dwa DATE 1/25/57

REJECTS RETURNED ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080004-9